

SERVICE BULLETIN

CHANNEL PROGRAMMER CP-SC-3

BULLETIN NUMBER: SB-0012
REVISION: 1-0-0
DATE: JAN 2005

PRODUCT DESCRIPTION: CHANNEL PROGRAMMER

DE REFERENCE / ECO: ECO# 829

| PRODUCTS EFFECTED: | Model Number | Board Versions |
|--------------------|--------------|------------------------|
| | CP-SC-3 | Sold prior to Nov 2003 |
| | | |
| | | |

SYMPTOMS: Will not allow programming of Code Numbers for the extra 2.5kHz Channel Steps.

CAUSE: New Firmware upgrade to recognize Hexadecimal switch in MSB position.

SOLUTION: Return the unit to the factory for a firmware upgrade.

| PARTS REQUIRED: | Qty | UOM | Description | Part Number | Designators |
|-----------------|-----|-----|-------------|-------------|-------------|
| | | | None | | |

RETURN REQUESTS: To have affected product returned to Daniels Electronics for servicing (or replacement, etc...), please contact the service department to obtain an RMA number and return shipping instructions at 1-800-664-4066

| REVISION HISTORY: | Rev Date | Description | |
|-------------------|----------|-------------|---------------|
| | 1-0-0 | 11/01/05 | First Release |