

SERVICE BULLETIN

CI-MP-4-00

BULLETIN NUMBER: SB-0013
REVISION: 1-0-0
DATE: FEB 2005

PRODUCT DESCRIPTION: P25 MODULE PROGRAMMER

DE REFERENCE / ECO: ECO# 838

PRODUCTS EFFECTED:	Model Number	Board Versions
	CI-MP-4-00	All versions

SYMPTOMS: RSS MT4D will display a run time error and fail to communicate with module when using USB to serial adapter.

CAUSE: An apparent incompatibility with some manufacturers of the USB Adapters and Daniels RSS.

SOLUTION: A compatibility table was created.

PARTS REQUIRED:	Qty	UOM	Description	Part Number	Designators
	none				

PROCEDURE: Use the following "USB to serial adapter compatibility table" on page 2.

REVISION HISTORY:	Rev	Date	Description
	1-0-0	23/02/2005	First Release

SERVICE BULLETIN

CI-MP-4-00

ADDITIONAL INFORMATION

USB to serial adapter compatibility table

Manufacturer	Address/Website	Phone No	Part No.
Access I/O Products Inc.	http://www.access-usa.com/ 10623 Roselle Street, San Diego, CA92121	(858) 5509559	USB-232
Sewell	http://www.sewelldirect.com/ 1106E 930S Provo, UT84660	(801) 3563823	USB to Serial Adaptor: SW-1301
BAFO Technologies	http://www.bafo.com 70 Ethel Road West Suite1 Piscataway, NJ 08854	sales@bafo.com	USB Adaptor: BF-810
ATEN Technology, Inc.	http://www.aten.com	(888) 9992836	USB to Serial: UC232A
BELKIN Corporation	http://www.belkin.com	(800) 2235546	Part # F5U109
GoldX Products Inc.	http://www.goldxproducts.com 2704 Palden Drive Auburn Hills, MI 48326	(866) 2446539	GXMU-1200