

# SERVICE BULLETIN

## MT-4D RECEIVERS

**BULLETIN NUMBER:** SB-0015  
**REVISION:** 1-0-0  
**DATE:** FEB 2005

**PRODUCT DESCRIPTION:** ALL MT-4D FAMILY AND VERSIONS

**DE REFERENCE / ECO:** ECO# 837

**PRODUCTS EFFECTED:**

Model Number

Board Versions

All MT-4D or MT-4R Radios  
using the RSS

All

**SYMPTOMS:**

"RSS MT-4D" will display model number error when trying to read/write to MT-4D unit

**CAUSE:**

Unit was inadvertently programmed with older MT-4R RSS that changed model number

**SOLUTION:**

Contact Service Dept. for software repair tool or to obtain an RMA# to return unit for repair.

**PARTS REQUIRED:**

Qty	UOM	Description	Part Number	Designators
none				

**PROCEDURE:**

The use of the Model Number Tool will change the model number from MT-4D to MT-4R or vice versa.

**RETURN REQUESTS:**

To have affected product returned to Daniels Electronics for servicing (or replacement, etc...), please contact the service department to obtain an RMA number and return shipping instructions at 1-800-664-4066 or email at [service@danelec.com](mailto:service@danelec.com)

**REVISION HISTORY:**

Rev	Date	Description
1-0-0	21/02/2005	First Release